



GREG BELL Lieutenant Governor

# State of Utah DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

#### Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

	Representatives Present During the Inspection:			
	Company	Mike Davis		
-	OGM	Joe Helfrich		

## **Inspection Report**

Permit Number:	C0410002
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, January 25, 2012
Start Date/Time:	01/25/2012 1:30:00 PM
End Date/Time:	01/25/2012 2:30:00 PM
Last Inspection:	Wednesday, December 07, 2011

Inspector: Joe Helfrich,

Weather: <u>Sunny cold slight breeze</u> InspectionID Report Number: <u>2999</u>

Accepted by: jhelfric

01/31/2012

Permitee: CANYON FUEL COMPANY Operator: CANYON FUEL COMPANY

Site: SUFCO MINE

Address: 597 SOUTH SR24, SALINA UT 84654

County: SEVIER

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

**Current Acreages** 

<b>Total Permitted</b>	720.48
<b>Total Disturbed</b>	48.43
Phase I	
Phase II	
Phase III	

M	line	ral	Ow	/ne	rst	nir

Federal

Types of Operations

✓ Underground☐ Surface

State Surface
County Loadout

☐ Fee ☐ Processing ☐ Other ☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The purpose of this site visit was to conduct a partial inspection of the SUFCO mine.

Inspector's Signature:

lóe Helfrićh,

Inspector ID Number: 1

Date

Tuesday, Janua



**Inspection Continuation Sheet** 

Permit Number: C0410002 Inspection Type: PARTIAL

Inspection Date: Wednesday, January 25, 2012

Page 2 of 3

### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers				
3.	Topsoil	<b>✓</b>		<b>~</b>	
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches	✓		<b>✓</b>	
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	<b>V</b>		<b>✓</b>	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0410002 Inspection Type: PARTIAL

Inspection Date: Wednesday, January 25, 2012

Page 3 of 3

#### 1. Permits, Change, Transfer, Renewal, Sale

The permittee is preparing a response to the Division's correspondence dated December21, 2011 for project 3 WG3950. Division staff assigned to this task met with Leland Roberts, Chris Hansen and Mike Davis on January 19th to discus the deficiencies note in the 12/21 letter.

#### 3. Topsoil

Topsoil from the development of the 4th west portals has been moved from its temporary location near the waste rock site to the permanent location with the other topsoil salvaged from the development of the waste rock site. The relocated topsoil should be seeded.

#### 6. Disposal of Excess Spoil, Fills, Benches

Waste rock from the development of the 4th west portals is being placed in the waste rock disposal site and is nearly complete.

#### 18. Support Facilities, Utility Installations

At the time of the inspection the belt line for the 4th west conveyor was being installed.